

# ProCal 21™

## CALCIUM, LIME & EFFLORESCENCE REMOVER

### FOR FLOORS - USE ONLY AS DIRECTED

ProCal 21™ consists of: 1 Bottle of ready to use ProCal 21™ and 1 Bottle of concentrated Clean Step™

**EQUIPMENT & MATERIALS YOU WILL NEED:**

Clean Step | Wringer pail | stationary pail | string mop | handheld scrub brush | sponge | deck brush | rotary floor machine (optional)



Important: Always wear protective gloves and eye wear during application process and \*organic vapor mask (in enclosed areas). Use under well-ventilated conditions.

Used on ceramic tile, porcelain tile, and most hard mineral surfaces (also used to remove most surface rust).



Before you begin: Test an area first. You will need to use Clean Step™ prepared in wringer pail [add 1 cup Clean Step™ to 2 gallons water]

**DIRECTIONS FOR USE (DO NOT USE PROCAL 21™ AS A CLEANER):**

**Step 1:** For spot removal, carefully pour a small amount of ProCal 21™ onto affected area, allowing up to 1 minute reaction time, then scrub with handheld scrub brush, or for larger areas pour ProCal 21™ into stationary pail then carefully mop out on to affected area (DO NOT SPLASH) and scrub with hard bristle deck brush. Repeat above until all affected areas are completely removed.

**Step 2:** Using prepared Clean Step™ in wringer pail, mop out and mix the two solutions together, or for spot removal use handheld sponge, then hose down the drain or mop up all remaining solutions.

A **'Thorough Rinsing'** of the area is now necessary (cold water will suffice).

**FOR STUBBORN OR HEAVIER DEPOSITS, REPEAT ABOVE STEPS UNTIL REMOVED**

*Safely removes most mineral deposit buildup from hard mineral surfaces*

**FIRST AID TREATMENT:** If splashed in eyes or on skin, flush thoroughly with water for 15 minutes.

**CAUTION:** Not For Use on Marble – Handle with Care – Extremely Corrosive

**KEEP OUT OF REACH OF CHILDREN**

**DO NOT USE PROCAL 21™ AS A CLEANER**

<< ONLY USE **CLEAN STEP™** AS YOUR REGULAR EVERYDAY CLEANER >>

*Cleaner is Safer™*